



NOTES:

1. NO HORIZONTAL ALIGNMENT CHANGE CAN BE MADE WITHIN THIS MANHOLE TYPE. USE ON GRADES 10% OR GREATER.
2. EACH JOINT OF PIPE BETWEEN HIGH VELOCITY MANHOLE & MANHOLE UPGRADE SHALL HAVE A THRUST COLLAR. SEE STD.NO. 6.12.

TOWN OF APEX
STANDARDS

EFFECTIVE: JULY 21, 2015

HIGH VELOCITY MANHOLE INVERT

STD. NO.

700.11

SHEET 1 OF 1